Repairing process of the Kumamoto castle towers





Foundation of the castle towers were not stone walls but reinforced concrete columns!





Corner tower named Iida-Maru





This building became very famous because it kept standing against the earthquake with a line of corner stones.








Corner stone like a column Aug. 2016 Jul. 2018

Sendai after seven years and a half since the 3.11 tsunami disaster



Visit: Sep. 3 - 6, 2018

Arahama primary school as a remain of 3.11 tsunami disaster











津波襲来までの経過を示すパネル展示

「失われた街」模型復元プロジェクトによる『記憶の街ワークショップin荒浜』完成模型 Residents have lost their home town completely, but they have just started to remind their memories.

Nothing remained in the Arahama beach, Sendai







Residents are coming back little by little into their Yuriage town, Natori city





復興まちづくり、がんばろう閖上







Yuriage town is on the half-way of reconstruction

















閖上港の漁船

名取市バスなとりんち

名取帀サポートセンターに併設された『閖上サロン